

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
SAS/04/18934/10	BR-005	Students' Union			Thermal Insulation	1118-10	Crocidolite/Amosite/Chrysotile	Buried beneath concrete floor slabs, no access into ducts. Review if there is a requirement to dig up or break up concrete floor.	Asbestos - Annual
001/JBL	BR-090	Joseph Banks Laboratories			GF Residue - West - Bitumen Adhesive		Chrysotile		Asbestos - Annual
002/JBL	BR-090	Joseph Banks Laboratories			GF Residue - West - Bitumen Adhesive		Chrysotile		Asbestos - Annual
003/JBL	BR-090	Joseph Banks Laboratories	Stair 1	JBL0W53	GF Stairs - West - Bitumen Adhesive		Chrysotile		Asbestos - Annual
004/JBL	BR-090	Joseph Banks Laboratories			GF Residue - East - Bitumen Adhesive		Chrysotile		Asbestos - Annual
007/JBL	BR-090	Joseph Banks Laboratories			1st Floor Residue to floor - Bitumen Adhesive		Chrysotile		Asbestos - Annual
001/MH	BR-091	Minster House			GF Residue - Bitumen Adhesive		Chrysotile		Asbestos - Annual
002/MH	BR-091	Minster House			1st Floor Residue - Bitumen Adhesive		Chrysotile		Asbestos - Annual
1091006	RI-002	Riseholme Conference Centre	Store	CON0007	Floor Tiles - Reinforced Composites	B-33966	Chrysotile	Floor tiles beneath floor covering, visually consistent with sample 2. (No Photo Available)	Asbestos - Annual
1016910	RI-002	Riseholme Conference Centre	Cleaners' Cupboard	CON0008	Floor Tiles - Reinforced Composites	B-33966	Chrysotile	Floor tiles to store room floor.	Asbestos - Annual
1016942	RI-002	Riseholme Conference Centre	Roof	CONRF	Skylights - Rope/Textile	B-33966	Chrysotile	Rope to skylights adjacent to wall.	Asbestos - Annual
1030512	RI-001	Riseholme Hall	Corridor	OLD0060	Stair Nosing Strip - Reinforced Composites	B-33965	Chrysotile	Black stair nosing.	Asbestos - Annual
1030531	RI-001	Riseholme Hall	Cupboard	OLD0065	Floor Covering - Reinforced Composites	B-33965	Chrysotile	Red floor tiles.	Asbestos - Annual
1030532	RI-001	Riseholme Hall	Corridor	OLD0060	Floor - Reinforced Composites	B-33965	Chrysotile	Composite floor tile sample.	Asbestos - Annual
1030534	RI-001	Riseholme Hall			Floor - Reinforced Composites	B-33965	Chrysotile	Floor tiles.	Asbestos - Annual
1030496	RI-001	Riseholme Hall	Practical Room	1.23	Floor Tiles - Reinforced Composites	B-33965	Chrysotile	Cream floor tiles under carpet.	Asbestos - Annual
1030499	RI-001	Riseholme Hall	Switchgear	OLD0071	Electrical Switch Gear - Rope/Textile	B-33965	Amosite/Chrysotile	No access into switch gear , therefore according to HSG 264 Asbestos assumed. No sample ref.	Asbestos - Annual
1030498	RI-001	Riseholme Hall	Switchgear	OLD0071	Board - Asbestos Insulating Board	B-33965	Amosite	Asbestos board to ceiling. Untreated in conditions.	Asbestos - Annual
1033117	RI-001	Riseholme Hall			Sky Light - Asbestos Textiles	B-33965	Amosite/Chrysotile	No access to sky lights therefore Asbestos is to be presumed in accordance with	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
1033126	RI-001	Riseholme Hall	Kitchen & Network Equipment	OLD2.11	Acoustic Sink Pad - Reinforced Composites	B-33965	Chrysotile	HSG264. Sink pad.	Asbestos - Annual
1059510	BR-003	Media, Humanities & Technology Building	Plant Room	GS0014	Gasket - Reinforced Composites	B-33969	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059513	BR-003	Media, Humanities & Technology Building	Control Room	MC1012	Gasket - Reinforced Composites	B-33969	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059517	BR-003	Media, Humanities & Technology Building	Air Handling Riser - East	SC2014	Gasket - Reinforced Composites	B-33969	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059519	BR-003	Media, Humanities & Technology Building	West Riser	TC3008	Gasket - Reinforced Composites	B-33969	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059266	BR-003	Media, Humanities & Technology Building	Chiller Compound	PC4004	Gasket - Reinforced Composites	B-33969	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059265	BR-003	Media, Humanities & Technology Building	Boiler Room	PC4016	Gasket - Reinforced Composites	B-33969	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059267	BR-003	Media, Humanities & Technology Building	Chiller Compound	PC4004	Gasket - Reinforced Composites	B-33969	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
1054092	BR-007	Science Centre	Store	SB006	Rope - Asbestos Textiles	B-33982	Chrysotile	your Management Plan or when circumstances change. White rope to top of cupboard. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054097	BR-007	Science Centre	Generic Laboratory 2	SB109	Boards - Asbestos Cement	B-33982	Chrysotile	Oven made of asbestos cement boards Visually consistent as sample 15. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054096	BR-007	Science Centre	Generic Laboratory 2	SB109	Boards - Asbestos Cement	B-33982	Chrysotile	Oven made of asbestos cement boards. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054095	BR-007	Science Centre	Generic Laboratory 2	SB109	Door Seal - Asbestos Textiles	B-33982	Chrysotile	Door seal to high temperature oven. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054094	BR-007	Science Centre	Generic Laboratory 2	SB109	Door Seal - Asbestos Textiles	B-33982	Chrysotile	Rope seal around the door. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
20005811	BR-007	Science Centre	Generic	SB109	Boiler Seal -	B-33982	Chrysotile	Oven seal, visually	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
			Laboratory 2		Asbestos Textiles			consistent with sample 13. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	
1059340	RI-064	Glass House 1	Glass House 1 Shed	RG10002	Boards - Asbestos Cement	B-34008	Chrysotile	Asbestos roofing sheet to shed attached to the Robinsons glasshouse. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059339	RI-064	Glass House 1	Glass House 1	RG10001	Boards - Asbestos Cement	B-34008	Chrysotile	Asbestos cement boards used as skirting to the Robinsons glasshouse only. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1125151	RI-062	Shed 4	Shed	RSH0001	Ceiling/Roof/Wall Panels - Asbestos Cement	B-34007	Chrysotile	Corrugated cement roof and wall panels. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059274	RI-033	Garden Cottage	Roof	GCRF	Downpipe - Asbestos Cement	B-33998	Chrysotile	1 run of asbestos cement downpipe. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1089608	RI-020	9 Riseholme Lane			Verge	B-33996	Amosite/Chrysotile	No access due to	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
1089607	RI-020	9 Riseholme Lane			Undercloaking - Asbestos Cement			height restrictions. Asbestos is presumed in accordance with HSG264.	
1089605	RI-020	9 Riseholme Lane			Ceiling Panelling to Porch - AIB	B-33996	Amosite	Ceiling panelling to porch. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054364	RI-019	7 Riseholme Lane			Damp Proof Course - Bitumen/Felts	B-33996	Chrysotile	Damp proof course. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054380	RI-019	7 Riseholme Lane			Cistern - Reinforced Composites	B-33995	Amosite	Shire toilet cistern. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054379	RI-019	7 Riseholme Lane			Roofing Felt - Bitumen/Felts	B-33995	Chrysotile	Mineral felt to garage visually consistent with sample 5. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054378	RI-019	7 Riseholme Lane			Roofing Felt - Bitumen/Felts	B-33995	Chrysotile	Roofing felt to single storey rear extension and porch. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054378	RI-019	7 Riseholme Lane			Roof Undercloaking - Asbestos Cement	B-33995	Amosite/Chrysotile	Unable to access due to height restriction	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
1054376	RI-019	7 Riseholme Lane			Soffit - Asbestos Insulating Board	B-33995	Amosite	therefore asbestos cement presumed as in accordance with HSG264, due to age of building (built 1961) Board is visually consistent with sample 4. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1054375	RI-019	7 Riseholme Lane			Board - Asbestos Insulating Board	B-33995	Amosite	Board to entrance porch. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059325	RI-018	3 Riseholme Lane			Roof - Asbestos Cement	B-33981	Chrysotile	Asbestos cement roofing sheets visually consistent with sample 1. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059328	RI-018	3 Riseholme Lane			Damp Proof Course - Reinforced Composites	B-33981	Chrysotile	Damp proof course. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1059327	RI-018	3 Riseholme Lane			Boards - Asbestos Insulating Board	B-33981	Chrysotile	Roofing. Part of soffit has been removed. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
1131987	RI-017	1 Riseholme Lane			Floor Tiles - Reinforced Composites	B-33994	Chrysotile	Brown floor tiles under carpet visually consistent with sample 2. Re-inspect the asbestos containing material	Asbestos - Annual
1131991	RI-017	1 Riseholme Lane			Floor Tiles - Reinforced Composites	B-33994	Chrysotile	Brown floor tiles under carpet visually consistent with sample 2. Re-inspect the asbestos containing material	Asbestos - Annual
1132492	RI-017	1 Riseholme Lane			Floor Tiles - Reinforced Composites	B-33994	Chrysotile	Brown floor tiles under carpet visually consistent with sample 2. Re-inspect the asbestos containing material	Asbestos - Annual
1131997	RI-017	1 Riseholme Lane			Floor Tiles - Reinforced Composites	B-33994	Chrysotile	Brown floor tiles under carpet. Re-inspect the asbestos containing material	Asbestos - Annual
1131999	RI-017	1 Riseholme Lane			Floor Tiles - Reinforced Composites	B-33994	Chrysotile	Brown floor tiles under carpet visually consistent with sample 2. Re-inspect the asbestos containing material	Asbestos - Annual
1132508	RI-017	1 Riseholme Lane			Verge Cloaking - Cement Products	B-33994	Chrysotile	Verge Cloaking to first floor and ground floor roof edge. Re-inspect the asbestos containing material	Asbestos - Annual
1132507	RI-017	1 Riseholme Lane			Soffits - Asbestos Insulating Board	B-33994	Chrysotile	Insulation board Soffits to ground and first floor gable ends. Re-inspect the asbestos containing material	Asbestos - Annual
1054775	RI-016	2 New Farm Cottages			Floor Tiles - Reinforced Composites	B-33933	Chrysotile	GF - Hall. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change	Asbestos - Annual
1054777	RI-016	2 New Farm Cottages			Floor Tiles - Reinforced Composites	B-33993	Chrysotile	GF - Lounge. Re-inspect the asbestos containing material on an annual basis in accordance with your Management	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
1054778	RI-016	2 New Farm Cottages			Floor Tiles - Reinforced Composites	B-33993	Chrysotile	Plan or when circumstances change GF - Dining Room Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change	Asbestos - Annual
1054783	RI-016	2 New Farm Cottages			Floor Tiles - Reinforced Composites	B-33993	Chrysotile	GF - Larder. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change	Asbestos - Annual
1054794	RI-016	2 New Farm Cottages			Verge Board - Asbestos Cement	B-33993	Chrysotile	External. Verge board above front door. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change	Asbestos - Annual
1054793	RI-016	2 New Farm Cottages			Soffits - Asbestos Insulating Board	B-33993	Amosite	Soffits underside of roof outside bedroom. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change	Asbestos - Annual
962823	RI-014	Lindsey Centre	Switchgear	LIN0053	Electrics - Asbestos Textiles	B-30079	Amosite/Chrysotile	No access within live electrics, therefore asbestos is presumed in accordance with HSG264. Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
962844	RI-014	Lindsey Centre	Plant Room	LIN0056	Paper Insulation - Paper/Cardboard	B-30079	Chrysotile	required to assist in the compilation of a management survey. Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
962845	RI-014	Lindsey Centre	Plant Room	LIN0056	Gaskets - Asbestos Textiles	B-30079	Chrysotile	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
962846	RI-014	Lindsey Centre	Plant Room	LIN0056	Rope - Asbestos Textiles	B-30079	Chrysotile	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
962865	RI-014	Lindsey Centre	Animal Lab	LIN0008	Gaskets - Asbestos Textiles	B-30079	Amosite/Chrysotile	No access to motor gaskets can visually be seen but no safe access due to height, therefore asbestos is presumed in accordance with HSG264. Remove all asbestos materials, prior to	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
962866	RI-014	Lindsey Centre	Animal Lab	LIN0008	Panels - Asbestos Cement	B-30079	Chrysotile	refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey. Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
962868	RI-014	Lindsey Centre	Prep Area	LIN0010	Sink Pad - Bitumen/Felts	B-30079	Chrysotile	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
962889	RI-014	Lindsey Centre	Dirty Wash Area & Store	LIN0020	Adhesive - Bitumen	B-30079	Chrysotile	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
962890	RI-014	Lindsey Centre	Dirty Wash Area & Store	LIN0020	Sink Pads - Bitumen/Felts	B-30079	Chrysotile	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
962852	RI-014	Lindsey Centre	Roof	LINRF	Flue Pipe - Asbestos Cement	B-30079	Chrysotile	materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey. Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
962847	RI-014	Lindsey Centre	Throughout	LINTT	Damp Proof Course - Bitumen/Felts	B-30079	Chrysotile	materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey. Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 months period stated within HSG264, the information collated will be required to assist in the compilation of a management survey.	Asbestos - Annual
1090188	RI-009	General Stores	Store	RGS0002	Floor Tile Adhesive - Bitumen/Felts	B-33990	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
1090187	RI-009	General Stores	Store	RGS0002	Floor Tiles - Reinforced Composites	B-33990	Chrysotile	Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances	Asbestos - Annual

Asbestos ID	Property Code	Property	Space Name	Space Number	Description	Survey	Asbestos	Remark	Inspected
1049093	RI-007	Stable Yard	Kitchen	RSY1005	Sink Pad - Bitumen/Felts	B-33974	Chrysotile	change. Re-inspect the asbestos containing material on an annual basis in accordance with your Management Plan or when circumstances change.	Asbestos - Annual
636866	BR-001	Minerva Building			Toilet Survey	25087	Crocidolite/Amosite/Chrysotile	1st Floor Male Toilets - Mastic to duct within ceiling void. Clay tiles to concrete floor. Tiled block walls. Timber riser panels and cupboards. Metal grid ceiling. Timber door and frames. Metal soffit. metal soil pipe Approx. Quantity = Unknown Product Type = Mastics Damage Extent = Good Cond. No Visible damage Surface Treatment = Composite materials - reinforced plastics, resins, floortiles etc	Asbestos - Annual
661856	BR-001	Minerva Building			Project No.25542 Survey	25542	Crocidolite/Amosite/Chrysotile	1st Floor MAle Toilet - Mastic to duct within ceiling void. Clay tiles to concrete floor. Tiled block walls. Timber riser panels and cupboards. Metal grid ceiling. Timber door and frames. Metal soffit. metal soil pipe. Product Type = Mastics Surface Treatment = Composite materials - reinforced plastics, resins, floortiles etc Extent of Damage = Good condition - no visible damage etc	Asbestos - Annual